Part-I

Performa For the Safety of School Building (To be filled by the Head of School/Institute)

1. 2.	Name of the School Location	: ANAND ISHER SR. SEC.PUBLIC SCHOOL	
2. 3.	Plot Area	: VPO Chhapar, Dist.Ludhiana.	
<i>3. 4.</i>	Plinth Area	: 76890.3 Sq. Mtr. (19 acres)	
		: (6397.354 + 2617.80 Sq. Mtrs= 9015.154 Sq.Mtrs))	
5.	Number of Storey	: Three	
6.	Year of Construction of Building	: G.Floor = 40 Years Old	
		F.Floor = 30 Years Old	
		S.Floor = 20 years Old	
7.	Supervision of The Qualified Engineer		
	The following details may be giv	ven:-	
	. a) Name of the Engineer	N.A	
	b) Address		
	 c) Set of Structure Drawing usea the construction if available. 	in	
	d) Name of Architect		
8.	Whether the building has been constructed for purpose of:-		
	a) School	(Yes/No)YESYES	
	b) Residential Purpose and converted		
	for use as a school.	(Yes/No) NO	
9.	Material used for Roof :-	Cement, Steel, Sand, Crasher & Waterproofing tiles	
	a) R.C.C. Slab	(Yes/No)YESYES	
	b) R.S. Joists and Batters	(Yes/No)NO	
	c) Wooden Joists and Batters	(Yes/No)NO	
10.	Material used for Walls :-	Bricks, Sand, Cement & Chips	
	a) Mud Mortar	(Yes/No)NO	
	b) Cement Mortar	(Yes/No)YES	
	c) Plaster (i)Lime Mortar	(Yes/No)NONO	
	(ii) Cement Mortar	(Yes/No)YES	
11.	Flooring :-	Marble, Bricks, P.C.C.	
	a) Conglomerate	(Yes/No) No	
	b) Terrazzo	(Yes/No)NoNo	
	c) Brick Paving	(Yes/No)For landing area	
12.	Detailed Drawing including dime		
	of the rooms along with size and location		
	of doors and windows.	Yes, (Ground floor, first floor & second floor	

Signature with stamp of ool
Arang Sile of the School Institute
Affiliated to CBSE Code-1630611

P.

P.T.O

Part-II

(To be filled by S.D.E. of P.W.D. B&R Department)

I have visited the above mentioned school on 04/66/1015 and have visually inspected it from all angles of safety and I found it fit for normal use as School Building.

In case any addition/alteration of expansion and modification of this building is to be carried out, the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls/foundations or sagging of roofs etc. Immediately inspection of the undersigned be arranged to check the stability of the building.

This building can be safely occupied for normal use upto_ year upto which it can be used)

Sub Divisional Engineer

Sub Divisional Engineer Constn. Sub Division No.1, P.W.D. B & R Br., Ludhian

05/06/2025 ਮਿਤੀ

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ 73-79 ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਪ੍ਰਿੰਸੀਪਲ ਆਫ ਆਨੰਦ ਇਸ਼ਰ ਸੀਨੀ. ਸੈਂਕੰ. ਪਬਲਿਕ ਸਕੂਲ, ਛਪਾਰ, ਜ਼ਿਲ੍ਹਾ ਲੁਧਿਆਣਾ ਨੂੰ ਉਹਨਾਂ ਦ ਬੇਨਤੀ ਪੱਤਰ ਨੰ: AISSPS/Corr/2025/6 ਮਿਤੀ 28.04.2025 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ 31.03.2026 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ:1, ਲੋ. ਨਿ. ਵਿ. ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ

ਅਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਉਖ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:1 ਲਧਿਆਣਾ।